

# Inspection Photos

Operator: Rim Operating  
API: 067-09184  
Date: 8/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward.





Photo 3. View of the southern project area facing eastward.





Photo 4. View of erosional rilling and channeling along the access road, up to 2ft wide and deep.





Photo 5. View of roadside erosion, BMPs are full of sediment and no longer functioning. Cut banks are not stabilized.



Photo 6. View of area where sediment discharges from the access road and flowing toward Spring Creek (across the road in inset).





Photo 7. View of the reference area comprised of sagebrush shrubland with squirrel tail, James galleta, and penstemon.