

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

08/26/2021

Document Number:

679604122**FIELD INSPECTION FORM**Loc ID 450827 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10177Name of Operator: ENERPLUS RESOURCES (USA) CORPORATIONAddress: 950 17TH STREET #2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                  | Comment               |
|-----------------|-------|------------------------|-----------------------|
| Everhart, Jacob |       | jeverhart@enerplus.com | Regulatory Compliance |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 450814      | WELL | PR     | 11/18/2020  | OW         | 123-44918 | POT O' GOLD 8-67-35-2C | PR          |
| 450817      | WELL | PR     | 11/18/2020  | OW         | 123-44921 | SLIGO 8-67-26-23C      | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | TANK LABELS/PLACARDS                                  |       |            |
| Comment:             | 6 tanks do not display contents. See attached photos. |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.h.               | Date: | 07/28/2021 |
| Type                 | WELLHEAD  |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY   |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Emission Control Device     | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Compressor                  | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Pump Jack                   | # 1 |       |                 |

|                       |     |       |  |
|-----------------------|-----|-------|--|
| Comment:              |     | Date: |  |
| Corrective Action:    |     | Date: |  |
| Type: Gas Meter Run   | # 2 |       |  |
| Comment:              |     | Date: |  |
| Corrective Action:    |     | Date: |  |
| Type: Bird Protectors | # 4 |       |  |
| Comment:              |     | Date: |  |
| Corrective Action:    |     | Date: |  |
| Type: Flare           | # 1 |       |  |
| Comment:              |     | Date: |  |
| Corrective Action:    |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 2 | 400 BBLs | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| OTHER              | 6 | 400 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  | UNKNOWN  |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares containment with water tanks. |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |



**Inspected Facilities**Facility ID: 450814 Type: WELL API Number: 123-44918 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 450817 Type: WELL API Number: 123-44921 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679603840. 1 out of 2 previous corrective actions assigned to this location have been resolved. 1 previous corrective has been re-assigned to this location with its original corrective action date. No new corrective actions were observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary<br/> **Weather Conditions: cloudy, dry ground<br/> On Thursday, August 26, 2021 at approximately 12:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at IRISH PAD N/A (Enerplus Resources), at location #: 450827 in WELD COUNTY Colorado.<br/> While there, I observed a producing facility.<br/> During this inspection the following possible compliance issues were observed:<br/> 1. 6 tanks do not display contents. Install sign to comply with Rule 605.h. (Corrective Action Date: July 28, 2021) See attached photos #5-10.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/> This is a summary of inspection report.</p> | santistb | 08/26/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 679604123    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517747">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517747</a> |