

Interim Reclamation and Stormwater Inspection

July 8, 2021 & August 23, 2021

Operator: EDGE ENERGY II LLC- #10671

Location ID: 456286

Inspection Document #: 697503168

Weld County, CO

NENE Section 29 T11N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

July 8, 2021 Inspection Photos

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 1. Photo taken from the southwestern location, facing North. Photo illustrates Common rye (*Secale cereale*) and Wheat (*Triticum aestivum*) throughout the interim reclamation areas, which is not the approved surface owner seed mix.



Photo 2. Photo taken from the topsoil stockpile along the southwestern location, facing North. See comments under Photo 1.



Photo 3. Photo illustrates a Common rye seed (far left, slender seed) and Wheat seeds (far 2 right, bigger seeds).

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 4. Photo taken from the northwestern location, facing Northeast. See comments under Photo 1.



Photo 5. Photo taken from the northern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 6. Photo taken south of the location, facing West. Photo illustrates Common Rye (red arrows) and Wheat (orange arrow) that has escaped off the interim reclamation areas and onto the adjacent reference area. It was also observed along the adjacent eastern and northwestern reference areas.



August 23, 2021 Inspection Photos



Photo 7. Google Earth aerial imagery from 6/11/2021. Photo illustrates the extent of Common rye and Wheat on 8/23/2021 that has escaped off the interim reclamation areas and onto the adjacent reference area. The extent was observed along the northwest, southwest and east. Note- interim reclamation has been performed but not in compliance with Rule 1003.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 8. Photo taken from the southwestern extent within the adjacent reference area. Photo illustrates a Common rye plant that has started to seed out.



Photo 9. Photo taken from just outside of the southeastern location, facing West. Photo illustrates the Operator mowed interim reclamation areas back in July and also mowed ~6' outside of the perimeter ditch and berm BMP.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 10. Photo taken from the eastern interim reclamation area, facing North. Photo illustrates Operator mowed interim reclamation areas. Common rye and Wheat are ~12-16" tall.



Photo 11. Photo taken with the reclamation area illustrates Common rye has started to flower. Not all Common rye was observed flowering within the reclamation areas, which indicates it has just started.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 12. Photo taken from the southern access road, facing North. Photo illustrates 2-3' weeds that need to be managed. It appears the access road was recently mowed, likely back in July.



Photo 13. Photo taken from the southern access road, facing South. See comments under Photo 12.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 14. Photo taken from the southern access road, facing Southeast. Photo illustrates a cut slope that has not been properly stabilized and erosion is evident (red arrows).



Photo 15. Photo taken from the southern access road, facing Northeast. See comments under Photo 14.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 16. Photo taken from the entrance of location, facing West. Photo illustrates the cattle guard has been damaged, as one wing is missing and the gate has been replaced with a pipe and rope.



Photo 17. Photo taken from the well location, facing North. Photo illustrates unused equipment.