

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2021

Submitted Date:

08/17/2021

Document Number:

695104763

FIELD INSPECTION FORM

Loc ID 325674 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900
City: HOUSTON State: TX Zip: 77002

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
7 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		miles.venzra@ikavenergy.com	
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215213	WELL	PR	02/01/2020	GW	067-06818	FEDERAL LAND BANK C 1	PR

General Comment:
THIS IS A FACILITY AND SURFACE EQUIPMENT INSPECTION. ANY CORRECTIVE ACTIONS FROM PREVIOUS INSPECTION THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 5: Natural gas engine exhaust from muffler on ground impacting soil and gravel.		
Corrective Action:	Remove impacted material and dispose in approved manner. COMPLY WITH RULE 606. THIS CA WAS NOTED ON INSPECTION DOC #693901484 AND HAS NOT BEEN ADDRESSED. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION. CA DATE HAS BEEN BACKDATED TO ORIGINAL CA DATE FROM PREVIOUS INSPECTION. IMMEDIATE ACTION IS REQUIRED.		Date:
Type	OTHER		
Comment:	PHOTO 4: PACKING ON WELLHEAD IS LEAKING. SPOKE WITH ERIC SILVA AT THE CONTROL CENTER. PUMPER ARRIVED ON LOCATION TO FIX LEAK WHILE I WAS STILL PERFORMING MY INSPECTION.		
Corrective Action:	REPAIR LEAK, DISPOSE OF PRODUCED WATER AROUND WELLHEAD. COMPLY WITH RULE 606.		Date: <u>08/18/2021</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215213 Type: WELL API Number: 067-06818 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402788842	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512553
695104769	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512539