

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2021

Submitted Date:

08/24/2021

Document Number:

688310994

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
309598 _____ Sherman, Susan _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16910
Name of Operator: CHURCHILL ENERGY INC
Address: 2435 REED STREET
City: LAKEWOOD State: CO Zip: 80214

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Jacobson, Eric		eric.jacobson@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Lindley, Trent		trent.lindley@state.co.us	
Schultz, Scott		soctt.schultz@coag.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218174	WELL	SI	09/01/2020	DSPW	073-06159	CHAMPLIN-LIMON 1-19	TA

General Comment:

Routine UIC Inspection, 5 year MIT is required at this time but operator not found

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	No Form 17 for 2021		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment: Weeds in tank berms.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: <u>09/24/2021</u>

Wells Served By Facilities Above

AirsID

API Number
073-06159
073-06163

API Number	AirsID

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 218174 Type: WELL API Number: 073-06159 Status: SI Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND
 TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 07/28/2016
 Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____

Comment: Overdue for five year MIT, 7/28/2016

Corrective Action: All injection wells which fail MIT or which are determined to lack mechanical integrity shall be shut in. Immediately shut in well and disconnect flowline or disable/LOTO injection pump. Date: 08/24/2021

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been shut in since 4/2018, can't find operator

Corrective Action: Submit required Form 7(s) to COGCC per Rule 309. Date: 09/20/2019

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
	Other	Adequate		
Comment	Produced water spill reclaimed area is fenced.			
Corrective Action				Date:

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: Chemical barrel by pump shed without BMP's

Corrective Action: Install BMP's or other secondary containment devices per Rule 906.d.(1).

Date: 11/27/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402790559	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513917
688311189	Churchill Energy Champlin-Limon 1-19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513905