

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2021

Submitted Date:

08/24/2021

Document Number:

688311159

FIELD INSPECTION FORMLoc ID 309599 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16910

Name of Operator: CHURCHILL ENERGY INC

Address: 2435 REED STREET

City: LAKEWOOD State: CO Zip: 80214

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| MacLaren, Joe | | joe.maclaren@state.co.us | |
| Lindley, Trent | | trent.lindley@state.co.us | |
| Jacobson, Eric | | eric.jacobson@state.co.us | |
| Quint, Craig | | craig.quint@state.co.us | |
| Schultz, Scott | | scott.schultz@coag.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 218178 | WELL | SI | 11/01/2019 | OW | 073-06163 | CHAMPLIN-LIMON 2-19 | TA |

General Comment:

LocationOverall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | lease sign on CR 3E | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--------------------------|-------|------------|
| Type | WEEDS | | |
| Comment: | location and access road | | |
| Corrective Action: | Comply with Rule 606 | Date: | 08/24/2021 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|-----------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Heater Treater | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # | | |
| Comment: | No Form 17 on file for 2021 | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| CRUDE OIL | 3 | 300 BBLs | | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| Earth | | | | Inadequate |
| Comment: | See attached photos | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o. | | | Date: 08/24/2021 |

Wells Served By Facilities Above

| API Number |
|------------|
| 073-06159 |
| 073-06163 |

AirsID

| API Number | AirsID |
|------------|--------|
|------------|--------|

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

Inspected FacilitiesFacility ID: 218178 Type: WELL API Number: 073-06163 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Gap in Form 7s, last production 4/1/2018, next reporting 11/1/2019 as SI up to 9/1/2020, no reporting after thatCorrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.
Submit required Form 7(s) to COGCC per Rule 413.

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------------|---|
| 402790564 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513920 |
| 688311188 | Churchill Energy Champlin-Limon 2-19 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513908 |