

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/30/2021

Submitted Date:

08/30/2021

Document Number:

696104943

**FIELD INSPECTION FORM**
 Loc ID 421830 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                | Comment         |
|--------------|-------|----------------------|-----------------|
| ,            |       | EHSRC@bonanzacrk.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 421846      | WELL | SI     | 09/01/2020  | OW         | 123-33088 | Critter Creek 12-08H | SI          |

**General Comment:**

This is a WELL / BATTERY inspection.  
 Well(s): 1: Shut-In | SI.  
 Battery: Inactive | Shut-down.

**Location**

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Lease Road:</b> |          |       |  |
| Type               | Access   |       |  |
| comment:           | Adequate |       |  |
| Corrective Action  | L        | Date: |  |

Overall Good: ☐

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             | Propane.             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | LOCATION                                  |       |  |
| Comment:           | Barbed wire.                              |       |  |
| Corrective Action: |   | Date: |  |
| Type               | PUMP JACK                                 |       |  |
| Comment:           | Iron mesh panel.                          |       |  |
| Corrective Action: |   | Date: |  |
| Type               | SEPARATOR                                 |       |  |
| Comment:           | Heater Treater surrounded by earth berms. |       |  |
| Corrective Action: |   | Date: |  |

|  |     |       |                 |
|--|-----|-------|-----------------|
| <b>Equipment:</b>  |     |       | corrective date |
| Type: Vertical Heater Treater  | # 1 |       |                 |
| Comment: Surrounded by protective shed.  |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Gas Meter Run  | # 1 |       |                 |
| Comment: Gas Sales.<br>Calibration card indicates NO calibration within last year.<br>Last calibration: 10/09/2018. Inactive. No production. |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Bradenhead   | # 1 |       |                 |
| Comment: Appears plumbed to surface.   |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Vertical Separator   | # 2 |       |                 |
| Comment:   |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Pump Jack  | # 1 |       |                 |
| Comment:   |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Deadman # & Marked   | # 4 |       |                 |
| Comment: 4 / 4: marked.  |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Flare  | # 1 |       |                 |
| Comment: Not in use. Inactive.   |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Horizontal Heated Separator  | # 0 |       |                 |
| Comment:   |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Emission Control Device  | # 1 |       |                 |
| Comment: Crude storage vapor line combustor. Controls crude oil tanks vapors.<br>Pilots: OFF   Shut-down.                                    |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Other  | # 3 |       |                 |
| Comment: 1: Electric power bank.<br>1: Line heater. Surrounded by protective shed.<br>1: Oil reycle pump. Surrounded by protective shed.     |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Ancillary equipment  | # 2 |       |                 |
| Comment: At Battery:<br>1: ECD scrubber.<br>1: Propane tank. Placards.   |     |       |                 |
| Corrective Action:   |     | Date: |                 |
| Type: Bird Protectors  | # 3 |       |                 |
| Comment:   |     |       |                 |
| Corrective Action:   |     | Date: |                 |

|                                 |   |       |
|---------------------------------|---|-------|
| Type: Vertical Heated Separator | # 0   |       |
| Comment:                        |   |       |
| Corrective Action:              |   | Date: |
| Type: Prime Mover               | # 1   |       |
| Comment:                        | Electric motor drives pump jack. Shut-down. |       |
| Corrective Action:              |   | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 400 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
| Earth              | Adequate                         | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | Shares berms w/ crude oil tanks. |                     |                     |             |
| Corrective Action: |                                  |                     |                     |             |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 7 | 400 BBLs | STEEL AST |         | 40.930308,-104.448755 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                           | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|------------------------------------|---------------------|---------------------|-------------|
| Earth              | Adequate                           | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | Shares berms w/ produced H2O tank. |                     |                     |             |
| Corrective Action: |                                    |                     |                     |             |

**Venting:**

|                    |    |  |
|--------------------|----|--|
| Yes/No             | NO |  |
| Comment:           |    |  |
| Corrective Action: |    |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 421846 Type: WELL API Number: 123-33088 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI.  
Observed production valves shut.  
COGCC records indicate last production: 08/2020.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/03/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 08/30/2021 at approximately 14:22 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: HIGHPOINT OPERATING CORPORATION<br/> Location Name: Critter Creek /12-08H<br/> Location ID: 421830<br/> Well Name(s):<br/> Critter Creek 12-08H.<br/> API: 05-123-33088.<br/> Location County: Weld County, Colorado<br/> Weather: Partly Sunny w/ haze, dry.</p> <p>While there, I observed:<br/> Well(s): 1: Shut-In   SI.<br/> Battery: Inactive   Shut-down.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 08/30/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696104944    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519463">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519463</a> |