

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2021

Submitted Date:

08/19/2021

Document Number:

699503103**FIELD INSPECTION FORM**Loc ID 320132 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 79905Name of Operator: SMITH OIL PROPERTIES INCAddress: PO BOX 219City: BYERS State: CO Zip: 80103**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shelley, Vicki	303-825-7405	smithoilprop@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202777	WELL	SI	11/01/2019	GW	001-08182	COAN 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: [Weeds unmanaged on location see pics](#)Corrective Action: [Comply with COGCC housekeeping rules.](#)Date: 09/13/2020Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: [Red AG fencing](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: [automation](#)

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

100 BBLS

Open Top

Comment: [netting repaired](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	unable to see if berm is acceptable until weed growth is addressed.			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 202777 Type: WELL API Number: 001-08182 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 10/19/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 8/19/21 at approximately 1125 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name-</p> <p>Company Name- Smith Oil Properties</p> <p>API- 05-001-08182</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>This is a follow up inspection from document # 700900280 Corrective Actions are Delinquent.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds unmanaged on location</p> <p>Comply with COGCC housekeeping rules. 8/14/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>Other corrective actions have been addressed, Unable to inspect if bull plug was installed due to weed growth. Netting on produced water tank appears to have been repaired, and dead animals removed. Signs are installed per COGCC rules, however some are not visible due to weed growth.</p> <p>This is a summary of inspection report.</p>	medinaj	08/19/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402790181	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513537
699503104	inspection pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513522