



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: OTHER  
 Comment: [weeds unmanaged on location, trash on location under overgrown weeds, fiberglass tank on location not being used, see pics.](#)  
 Corrective Action: [Comply with COGCC housekeeping rules.](#)

Date: 07/10/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type: WELLHEAD

Comment: [Red AG fencing](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: <a href="#">automation</a>			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment: <a href="#">Plumbed to surface</a>			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**

Facility ID: 202785 Type: WELL API Number: 001-08190 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/25/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On 8/19/21 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Randall 22-2                      Company Name- KPK                      API- 05-001-08190                      In Adams County Colorado.                      While there, I observed PR well                      This is a follow up inspection from document # 700900206 Corrective Actions are Delinquent.                      During this inspection the following possible compliance issues were observed:                      weeds unmanaged on location, trash on location under overgrown weeds, fiberglass tank on location not being used, see pics.                      Comply with COGCC housekeeping rules 7/10/20                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      Other corrective actions have been addressed.                      This is a summary of inspection report.</p>	medinaj	08/19/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402790185	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513539">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513539</a>
699503112	Inspection pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513526">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513526</a>