

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2021

Submitted Date:

08/20/2021

Document Number:

699503115

FIELD INSPECTION FORMLoc ID 320112 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		JH@p3petro.com	
Canfield, Chris		chris.canfield@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
		fbair@p3petro.com	
		jmustacchia@p3petro.com	
		JM@p3petro.com	
		khubbard@p3petro.com	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202658	WELL	PR	05/01/2019	GW	001-08063	HORTH 41-15 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Old tank battery signs with HRM resources, and Noble Nergy need to be removed or covered with correct information.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	OTHER		
Comment:	Weeds unmanaged on location, trash stored in separator house see pics.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	06/25/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Red agricultural fencing		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Unable to verify when gas meter run was last calibrated due to weed growth on location.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Some markings hard to see due to weed growth.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	Gas meter run, and plunger lift automation equipment.	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	BV CONCRETE		,
Comment:	Label with capacity is faded and needs to be replaced.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		,
Comment:	Capacity labels on oil tank are faded, and damaged, need to be replaced.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with BV.			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 202658 Type: WELL API Number: 001-08063 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/29/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Annual bradenhead test is not current. Contact COGCC engineering.08/30/2021Corrective Action: Comply with COGCC annual bradenhead test rules.

Date:

Environmental**Spills/Releases:**Type of Spill: CONDENSATEEstimated Spill Volume: 5

Comment: Spill approximately 8' X 26' discovered on east side of tank battery between oil tank, and produced water buried vault see pics 1,2,3,4. Possible underground leak from flowline see pic 3. Location is located near a dry creek bed approximately 1/4 mile from spill.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.Date: 08/20/2021Reportable: YESGPS: Lat 39.696300Long -104.529865

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On 8/20/21 at approximately 1030 I, Inspector Justin Medina conducted an on-site inspection at:

Well Name- Horth 41-15 1

Company Name- P3

API- 05-001-08063

In Adams County Colorado.

While there, I observed PR well.

This is a follow up inspection from document # 700900150 Corrective Actions are Delinquent

During this inspection the following possible compliance issues were observed:

Weeds unmanaged on location, trash stored in separator house see pics.

Comply with COGCC housekeeping rules 6/25/2020

Spill approximately 8' X 26' discovered on east side of tank battery between oil tank, and produced water buried vault see pics 1,2,3,4. Possible underground leak from flowline see pic 3. Location is located near a dry creek bed approximately 1/4 mile from spill.

Control and contain spills/releases and clean up per Rule 912.a. 8/20/21

Annual bradenhead test is not current. Contact COGCC engineering.

Comply with COGCC annual bradenhead test rules.8/30/21

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

At time of inspection weather conditions were windy, warm, recent rain.

This is a summary of inspection report.

medinaj

08/20/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402790187	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513541
699503116	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513528