

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2021

Submitted Date:

08/31/2021

Document Number:

700600289**FIELD INSPECTION FORM**Loc ID 309123 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone        | Email                     | Comment                         |
|--------------------|--------------|---------------------------|---------------------------------|
| Mack, Ronald       |              | rmack@ogrisop.com         | <a href="#">All Inspections</a> |
| Santistevan, Vince |              | vsantistevan@ogrisop.com  | <a href="#">All Inspections</a> |
| Fitzgerald, Edie   | 719-859-1394 | efitzgerald@ogrisop.com   | <a href="#">All Inspections</a> |
| Beardslee, Tom     |              | tom.beardslee@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 288298      | WELL | PR     | 06/04/2007  | GW         | 071-09112 | GOLDEN EAGLE 29-6  | EI          |
| 292688      | PIT  | AC     | 09/03/2008  |            | -         | GOLDEN EAGLE 29-06 | AC          |

**General Comment:**

[This is an environmental inspection only. Any corrective actions from previous inspections are still in effect.](#)

[Produced water pit appears to contain oily waste. See corrective action.](#)

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 288298 | Type: | WELL | API Number: | 071-09112 | Status: | PR | Insp. Status: | EI |
|                      |        |       |      |             |           |         |    |               |    |
| Facility ID:         | 292688 | Type: | PIT  | API Number: | -         | Status: | AC | Insp. Status: | AC |
|                      |        |       |      |             |           |         |    |               |    |

## Reclamation - Storm Water - Pit

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 292688Lat: 37.144659Long: -104.913254Reference Point: SEOther: Length: Width: **Lining:**Liner Type: OtherLiner Condition: Comment: Unlined produced water pit appears to have oily waste in it. See attached photos.

Corrective Action

Operator shall sample liquid in pit for COGCC Table 915-1 Organic Compounds in Groundwater and TPH (C6-C36) and submit via Field Inspection Resolution Request (FIRR) in response to this inspection. Corrective Action date is for collecting samples.

Date: 09/06/2021**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: 

Corrective Action

Date: 

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
|         | 292688      | 2059201    |                 |
|         | 292688      | 2059201    |                 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700600290    | Inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519879</a> |