

Inspection Photos  
Location Name: Dungan 32-5 #5-1  
API: 05-007-06196



Well sign does not meet the requirements of Rule 605.d.

Standing water observed around well head. No other standing water was observed during this inspection.

**Inspection Photos**  
**Location Name: Dungan 32-5 #5-1**  
**API: 05-007-06196**



**Concrete pad and surrounding gravel are stained.**



**Dungan 32-5 #5-1 location photo.**

Inspection Photos  
Location Name: Dungan 32-5 #5-1  
API: 05-007-06196



AST signs list previous operator.



Southern AST has illegible labels.