

Inspection Photos

Operator: Kinder Morgan
API: 083-06573
Date: 8/31/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with rubber rabbitbrush, Indian ricegrass, snakeweed, and western wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of rock BMP in the northwestern project area (facing downslope), that is full of sediment and eroding around the rock-check is occurring.



Photo 5. View of another area where rock-check is overflowing and no-longer functioning.



Photo 6. View of another failed rock-check full of sediment with erosion continuing within channel.



Photo 7. View of reference area comprised of pinyon and juniper woodland with cliffrose, serviceberry, Indian ricegrass, Eaton's penstemon, and gambel oaks.