

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Burnett #2-1 location photo.

Damp soil along eastern edge of location.

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Area where Spill/Release Point ID #480579 breached secondary containment berm.



Crew working within secondary containment berm.

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Damp soil extends beyond location fence.



Damp soil and staining along eastern edge of location.

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Areas along eastern edge of location are damp and stained.



Stained vegetation and damp soil along eastern edge of the location.