

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2021

Submitted Date:

09/05/2021

Document Number:

696104971**FIELD INSPECTION FORM**Loc ID 415256 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415412	WELL	SI	08/01/2020	OW	123-31053	CRITTER CREEK 4-09H	SI

General Comment:[This is a WELL / BATTERY inspection.](#)[Well\(s\): 1: Shut-In | SI.](#)[Battery: Inactive | Shut-down.](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Heater Treater surrounded by earth berms.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron mesh panel.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 4		corrective date
---------------------------	-----	--	-----------------

Comment:	At Battery site: 1: ECD scrubber. 1: Electric power bank. 1: Line heater. Surrounded by protective shed. 1: Oil reycle pump. Surrounded by protective shed.				
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:	4 / 4: marked.				
Corrective Action:				Date:	
Type: Vertical Heater Treater	# 1				
Comment:	Surrounded by protective shed.				
Corrective Action:				Date:	
Type: Flare	# 1				
Comment:	Not in use. Inactive.				
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Electric motor drives pump jack. Shut-down.				
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:	Crude storage vapor line combustor. Controls crude oil tanks vapors. Pilots: OFF Shut-down.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	
Type: Vertical Separator	# 3				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Gas Sales. Calibration card indicates NO calibration within last year. Last calibration: 08/27/2020. Inactive. No production.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ crude oil tanks.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	400 BBLS	STEEL AST		40.930502,-104.430668

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ produced H2O tank.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 415412 Type: WELL API Number: 123-31053 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment:

Shut-In | SI.
Observed production valves shut.
COGCC records indicate last production: 07/2020.

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/04/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
COGCC Inspection Report Summary: On FRI 09/03/2021 at approximately 14:05 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: CRITTER CREEK /4-09H Location ID: 415256 Well Name(s): Critter Creek 4-09H. API: 05-123-31053. Location County: Weld County, Colorado Weather: Partly Sunny, dry. While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down. During this inspection, NO possible compliance issues were observed. This is a summary of the inspection report.	evinsb	09/05/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104972	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524301