

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2021

Submitted Date:

08/30/2021

Document Number:

696203107**FIELD INSPECTION FORM**

Loc ID 335889	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1001 17TH STREET #1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				
<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>				

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335889	LOCATION	AC			-	Cascade Creek 697-09-61	RI

**General Comment:**

On 8/23/2021, Reclamation Specialist Trujillo conducted a stormwater inspection at Laramie Energy's Cascade Creek 697-09-61 location in Garfield County, Colorado.

This inspection is also a followup to:  
 #696201787 dated 9/16/2020;  
 #696201980 dated 11/2/2020;  
 #696202122 dated 12/8/2020;  
 and #696202928 dated 7/12/2021 to document compliance with the following corrective actions:

1002.f: Stormwater

This inspection is also a followup to Resolution #402765194 stating "CA Completed".

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective Actions.

Refer to the "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Blankets						

Comment: It was observed in this inspection that Operator has implemented erosion control blankets on the slopes of the north and west end of the Location; however, there are large areas where BMPs to protect and stabilize the slopes remain missing or insufficient.

Work remains incomplete and Location remains out of compliance with Rule 1002.f.

Corrective Action: COGCC acknowledges the work performed to address the corrective action, and is requesting Operator submit an update on a FIRR, as to when BMPs to stabilize the remaining slopes will be implemented, and work completed.

Date: 09/02/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402797186	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519445</a>
696203108	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519433">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519433</a>