

**LOCIN OIL CORPORATION**  
**N. DOUGLAS CREEK-61S101W 33NENW**  
**Location # 315416**



**LOCIN OIL CORPORATION  
N. DOUGLAS CREEK-61S101W 33NENW  
Location # 315416**



**Erosion of berm ground base and under cutting ground under the tank.**

**LOCIN OIL CORPORATION  
N. DOUGLAS CREEK-61S101W 33NENW  
Location # 315416**



**Contents faded and not visible from distance.**



**Water not a proper content name.**

**LOCIN OIL CORPORATION  
N. DOUGLAS CREEK-61S101W 33NENW  
Location # 315416**



**Access road has storm water erosion and sediment back filled ditches.**



**Dead weed debris on location and roadway.**

**LOCIN OIL CORPORATION  
N. DOUGLAS CREEK-61S101W 33NENW  
Location # 315416**



**Access road has storm water erosion and sediment back filled ditches.**

**Access road has storm water erosion and sediment back filled ditches.**