

Inspection Photos

API: 071-07414

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 9/3/2021

Inspection Photos



Photo 1. There is vehicle rutting and erosion along the road. The white hard hat is placed in the vehicle rut for scale. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 9/3/2021

Inspection Photos



Photo 2. There is vehicle rutting and erosion along the road. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 9/3/2021

Inspection Photos



Photo 3. Stormwater is not being diverted toward the culvert (red arrow) and is flowing across the road causing erosion. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 9/3/2021

Inspection Photos



Photo 4. There is vehicle rutting occurring along the road which will only worsen if not repaired. The roads need to be maintained. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 9/3/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 9/3/2021