

Inspection Photos

API: 071-07412

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 9/3/2021

Inspection Photos



Photo 1. Facing back down the access road shows vehicle rutting and erosion. This issue has previously been documented and needs to be repaired and prevented. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 9/3/2021

Inspection Photos



Photo 2. Storm water erosion is occurring down the side of the road. BMP's need to be installed to prevent erosion. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 9/3/2021

Inspection Photos



Photo 3. Storm water is not directed toward the culvert and the culvert is damaged.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 9/3/2021

Inspection Photos



Photo 4. Facing along the access road toward the location. Storm water erosion is occurring down the side of the road. BMP's need to be installed to prevent erosion. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 9/3/2021

Inspection Photos



Photo 5. Facing toward the location.



Inspection Photos



Photo 6. There is stained gravel around the wellhead indicating a previous leak. This area needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07412 | Date: 9/3/2021