

Inspection Photos

API: 071-06130

Operator: OGRIS OPERATING LLC

Inspection Date: 9/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021

Inspection Photos



Photo 1. Facing southwest along the main road. The road has been regraded since the previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021

Inspection Photos



Photo 2. There are areas of the road that are still not stabilized after recent grading operations. There is vehicle rutting and stormwater is not directed toward the culvert shown at red arrow. Areas of rutting need to be stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021

Inspection Photos



Photo 3. This culvert along the road was repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021

Inspection Photos



Photo 4. Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021

Inspection Photos



Photo 5. Facing toward the location. Erosion is occurring along side of the road at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021

Inspection Photos



Photo 6. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 9/3/2021