

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2021

Submitted Date:

09/07/2021

Document Number:

690202040

**FIELD INSPECTION FORM**

Loc ID 307280 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		timothy.thomsen@state.co.us	
		rmack@ogrisop.com	
		efitzgerald@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217354	WELL	PR	01/01/1995	GW	071-06130	APACHE CANYON 14-1	RI

**General Comment:**

This is a follow up of the previous stormwater management inspections; #690201263, #690201547, #690201811. The corrective action of the previous inspections have not been performed. See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The road was graded and culvert maintenance has been performed. There are areas of the road that are still not stabilized after recent grading operations. There is vehicle rutting and stormwater is not properly diverted. Repairing the road only by grading is not sufficient. Areas of erosion along the access road must be repaired and properly stabilized. This issue has been previously observed and needs to be prevented. BMP's must be implemented in accordance with good engineering practice and must be maintained. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/30/2021

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">There was work in process further down the canyon road.</span>	CostaR	09/07/2021
<span style="color: blue;">Change of Operator is listed as OGRIS OPERATING LLC.</span>	CostaR	09/07/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202041	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525307">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525307</a>