

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2021

Submitted Date:

09/03/2021

Document Number:

688800992

FIELD INSPECTION FORM

 Loc ID 312051 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10679
 Name of Operator: LOGOS OPERATING LLC
 Address: 2010 AFTON PLACE
 City: FARMINGTON State: NM Zip: 87401
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rowley, Darren		drowley@logosresourcesllc.com	All inspections
		regulatory@logosresourcesllc.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216532	WELL	TA	05/01/2019	GW	067-08138	BONDAD 33-9 22A	EI
480361	SPILL OR RELEASE	AC	08/05/2021		-	SPILL/RELEASE POINT	EI

General Comment:

On August 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Bondad 33-9 #22A. For the most recent field inspection report of this facility, please refer to document #693903486. This site visit was performed to follow up on Spill/Release Point ID #480361.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to separator.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.128938,-107.799315
Comment:	PBV information taken from previous inspection reports of this facility. PBV has been removed.				
Corrective Action:					Date:

Paint

Condition _____

Other (Content) _____

Other (Capacity) 125 bbl

Other (Type) _____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:	Secondary containment information taken from previous inspection reports. Secondary containment has been removed.	
Corrective Action:		Date:

Wells Served By Facilities Above

AirsID

API Number
067-08138

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216532 Type: WELL API Number: 067-08138 Status: TA Insp. Status: EI

Facility ID: 480361 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 1

Comment: Please refer to Spill/Release Point ID #480361 for more information regarding this release. Operator reported spill as a precaution. Rule 912.b.(1) reporting thresholds were reportedly not met.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Per Rule 912.e.(1) the operator will submit a supplemental Form 19 to close Spill/Release Point ID #480361 with work proceeding under REM Project #19542.

Date: 10/01/2021

Reportable: NO GPS: Lat 37.128935 Long -107.799304

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: PBV and secondary containment berm have been removed as part of REM #19542.

Corrective Action: Provide a Supplemental Form 27 to update project file with analytical results and work conducted.

Date: 10/01/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date:
Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On August 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Bondad 33-9 #22A. For the most recent field inspection report of this facility, please refer to document #693903486. This site visit was performed to follow up on Spill/Release Point ID #480361.</p> <p>The 125 bbl. PBV has been removed from the location as part of REM #19542. The operator will provide an update of work completed to date and provide analytical results upon receipt. The operator will submit a Supplemental Form 19 to close Spill/Release Point ID #480361 with work proceeding under REM Project #19542.</p>	hughesjo	09/03/2021

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402802801	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524223
688800993	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524207