

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2021

Submitted Date:

09/07/2021

Document Number:

690202034

**FIELD INSPECTION FORM**

Loc ID 308702 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                   | Comment |
|----------------|-------|-------------------------|---------|
|                |       | efitzgerald@ogrisop.com |         |
|                |       | rmack@ogrisop.com       |         |
| ATWATER BONNIE |       | batwater@ogrisop.com    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 279261      | WELL | SI     | 10/01/2017  | GW         | 071-08482 | APACHE CANYON 13-11 | SI          |

**General Comment:**

This is a follow up stormwater management inspection.  
See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |                      |  |             |
|--------------------|----------------------|--|-------------|
| Comment:           | <input type="text"/> |  |             |
| Corrective Action: | <input type="text"/> |  | Date: _____ |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | OTHER  |       |            |
| Comment:           | There is a piece of rebar stuck in the road which could puncture a tire. |       |            |
| Corrective Action: | Remove metal rebar from roadway.   | Date: | 09/10/2021 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 279261 Type: WELL API Number: 071-08482 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Failed MIT - See document #402700719.  
Rule 417 f. - "All Wells which lack mechanical integrity, as determined through a mechanical integrity test, or other means, will be repaired or Plugged and Abandoned within 6 months."

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: There is erosion occurring along the access road. Stormwater is not properly diverted and there are insufficient BMP's to prevent erosion. Areas of erosion need to be repaired and stabilized. Previous corrective action was not performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/23/2020

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <span style="color: blue;">Change of Operator is listed as OGRIS OPERATING LLC.</span> | CostaR | 09/07/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402804136    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525310">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525310</a> |
| 690202035    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525304">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525304</a> |