

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2021

Submitted Date:

09/14/2021

Document Number:

699304269

FIELD INSPECTION FORM

Loc ID 333133 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		tmouret@p3petro.com	
,		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241406	WELL	SI	08/01/2020	OW	123-09195	OSKARSON 3	SI

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	weeds will need to be addressed in the near future			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	unused electric panel leaning on fence			
Corrective Action:	Comply with Rule 603.f, New Rule is 606			Date: 12/14/2020
Type	OTHER			
Comment:	Stained soil around WH, Properly dispose of oily waste.			
Corrective Action:	Comply with Rule 907.e, New Rule 905.e			Date: 12/14/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Chainlink			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	fabricated steel pipe			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead			# 1	corrective date
Comment:			appears to be plumbed to surface	
Corrective Action:			Date:	
Type: Prime Mover			# 1	
Comment:			electric motor	

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	meter box, electric panel and transformers		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241406 Type: WELL API Number: 123-09195 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/27/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Submit test information to the COGCC. appears to be plumbed to surface.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/14/2021 at approximately 1140 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Painted Pegasus Petroleum LLC location: Oskarson #3 at API #05-123-09195 in Weld County Colorado. Follow up to Doc #699302553 & 699303852.</p> <p>While there, I observed a wellsite. SI at the time of inspection all valves are closed and the electric power is off.</p> <p>During this inspection the following possible compliance issues were observed and are now delinquent:</p> <p>603.f housekeeping: unused electric panel leaning on fence, CA date 12 14 2020.</p> <p>907.e housekeeping: stained soil around WH, CA date 12-14-2020 .</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	09/14/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304270	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5530995