

Inspection Photos
Operator: Petrox
API: 007-06213
Date: 9/13/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, gambel oak, Woods rose, and mugwort.



Photo 3. View of rilling erosion occurring within the northern cut-slope.



Photo 4. View of Canada thistles (approx. 75) on the northern cut-slope.



Photo 5. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, Sandberg bluegrass, and serviceberry.