

Inspection Photos  
Operator: Petrox  
Facility: 007-06235  
Date: 9/13/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of kochia growing up to 4-foot tall on the well pad cut-slope. Little desirable vegetation observed here.



Photo 3. View of cable debris on the well pad.



Photo 4. View of musk thistles (approx. 100) observed within the project area, largely in a post-flowering condition and dispersing seed.



Photo 5. View of the southeastern fill slope from the southeastern corner facing northward. Desirable vegetation not observed. Dense prickly lettuce and field bindweed observable in photo.



Photo 6. View of the southeastern project area facing southward from the well pad corner. Little to no desirable vegetation observed, as reclamation areas are infested with prickly lettuce and field bindweed.



Photo 7. View of the reference area comprised of mixed grass field, with ponderosa pine forest, and western wheatgrass, smooth brome, serviceberry, and gambel oak in the understory.