


Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Pic 1 Rig on location




Pic 2 tubing laying on ground

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Pic 3 no Blow out preventer installed on wellhead.



Pic 4 No blow out preventer installed on wellhead

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Pic 5 no blow out preventer installed on wellhead




Pic 6 rig

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Pic 7 no containment under tubing



Pic 8 proximity of rig to residence was approx. 210' measured with wheel.

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Pic 9 doghouse trailer on location



Pic 10 vehicle on location

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664

Sep 15, 2021 at 2:11:22 PM
39.983612,-104.530471
8420 E 160th Ave
Keenesburg CO 80643
United States
COGCC



Pic 11 vehicle on location

Sep 15, 2021 at 4:01:01 PM
39.983545,-104.530107
8420 E 160th Ave
Keenesburg CO 80643
United States
COGCC



Pic 12 installation of BOP @ approx. 1630

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Pic 13 rig crew laying down tubing.