

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2021

Submitted Date:

09/09/2021

Document Number:

689806352**FIELD INSPECTION FORM**Loc ID 324754 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Boyer, David	303-994-0000	david@d90energy.com	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296567	WELL	PR	10/01/2020	OW	057-06469	SPICER 3-32H	PR

**General Comment:**

Routine follow up inspection. Follow up to inspection from 5/18/2021 document number 689805813. No corrective actions appear to have been made. Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676753, form remains In Process.

Compliance issues observed:  
tank battery, entrance, wellhead signs incomplete/inaccurate

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/11/2021
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/11/2021

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 296567 Type: WELL API Number: 057-06469 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402806999	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527778">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527778</a>
689806353	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527757</a>