

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2021

Submitted Date:

09/09/2021

Document Number:

700703207

FIELD INSPECTION FORM

Loc ID 335612 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

3 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Thomson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287170	WELL	PR	12/31/2008	GW	103-10908	FEDERAL RGU 13-36-198	PR
294085	WELL	PR	02/01/2021	GW	103-11147	FEDERAL RGU 43-35-198	PR
294088	WELL	PR	12/26/2007	GW	103-11148	FEDERAL RGU 44-35-198	PR
294089	WELL	PR	12/26/2007	GW	103-11149	FEDERAL RGU 343-35-198	PR
294091	WELL	PR	01/01/2021	GW	103-11150	FEDERAL RGU 344-35-198	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 9/9/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RGU 13-36-198, at Location # 335612 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Access road and location show signs of lack of stabilization/compaction, erosion and sediment migration off of location.
2. Dehy burner assembly is open for wildlife to enter.
3. One quad unit horizontal separators includes two glycol storage tanks, approximately 174" x 32" x 41" = 23.5 BBLS x 2 and one single separator unit includes one glycol storage tank, approximately 118" x 36" x 33" = 14.4 BBLS, storage vessels contain no labeling to specify capacity or chemical hazard information.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	See storm water		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	One quad unit horizontal separators includes two glycol storage tanks, approximately 174" x 32" x 41" = 23.5 BBLS x 2 and one single separator unit includes one glycol storage tank, approximately 118" x 36" x 33" = 14.4 BBLS, storage vessels contain no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Comply with rule 605.h		Date: 12/09/2021
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Ancillary equipment	# 3	corrective date

Comment:	Two chemical tanks in plastic containments and One 500 gallon methanol tank in metal containment			Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 5				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bradenhead	# 5				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 5				
Comment:				Date:	
Corrective Action:				Date:	
Type: Dehydrator	# 1				
Comment:	Dehy burner assembly is open for wildlife to enter.			Date:	
Corrective Action:	Eliminate wildlife access			Date:	09/24/2021
Type: Bird Protectors	# 8				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	<u>287170</u>	Type:	<u>WELL</u>	API Number:	<u>103-10908</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>294085</u>	Type:	<u>WELL</u>	API Number:	<u>103-11147</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>294088</u>	Type:	<u>WELL</u>	API Number:	<u>103-11148</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>294089</u>	Type:	<u>WELL</u>	API Number:	<u>103-11149</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>294091</u>	Type:	<u>WELL</u>	API Number:	<u>103-11150</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
Compaction	Fail					

Comment: 1. Access road and location show signs of lack of stabilization/compaction, erosion and sediment migration off of location.

Corrective Action: Install or repair required BMPs

Date: 10/15/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402806917	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527688
700703211	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527682