

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2021

Submitted Date:

09/16/2021

Document Number:

699104440

FIELD INSPECTION FORM

Loc ID 333274 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297652	WELL	PR	09/01/2009	OW	123-28024	HIGHPOINTE 10LD	PR
297653	WELL	PR	09/01/2009	OW	123-28025	HIGHPOINTE 10PD	PR
297658	WELL	PR	06/01/2021	OW	123-28029	HIGHPOINTE 10KD	PR
297671	WELL	PR	09/01/2009	OW	123-28033	HIGHPOINTE 10B	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil needs to be removed. See attached photo		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e	Date:	09/23/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	Other	#		corrective date
Comment:	Master valve appears to be leaking. Fix or replaced. See attached photo			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: 09/23/2021
Type:	Bradenhead	# 4		
Comment:	Appear to be plumbed to surface			
Corrective Action:			Date:	
Type:	Plunger Lift	# 4		
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 297652 Type: WELL API Number: 123-28024 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/20/2020 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Submit reports
 Corrective Action: _____ Date: _____

Facility ID: 297653 Type: WELL API Number: 123-28025 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/20/2020 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Submit reports
 Corrective Action: _____ Date: _____

Facility ID: 297658 Type: WELL API Number: 123-28029 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/20/2020 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Submit reports
 Corrective Action: _____ Date: _____

Facility ID: 297671 Type: WELL API Number: 123-28033 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/20/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/14/21 at approximately 1137hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Highpointe-65N67W10SESW of PDC Energy, at Location ID # 333274 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained soil needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 9/23/21 Master valve appears to be leaking. Fix or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 9/23/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	09/16/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104441	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5532779