

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2021

Submitted Date:

09/14/2021

Document Number:

699803603

FIELD INSPECTION FORMLoc ID 334996 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297605	WELL	PR	01/23/2009	GW	045-16888	SAVAGE 20-16BB (PP20)	PR
297664	WELL	PR	01/10/2009	GW	045-16910	SAVAGE 20-9BB (PP20)	PR
297665	WELL	PR	01/23/2009	GW	045-16911	SAVAGE 20-16 (PP20)	PR
297666	WELL	PR	01/10/2009	GW	045-16912	SAVAGE 20-15(PP20)	PR
297667	WELL	PR	01/10/2009	GW	045-16913	SAVAGE 20-15BB (PP20)	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 9/13/21 at approximately 12:30 hours, I, Inspector Corey De Paolo,

Conducted a follow up inspection at CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE,

Location #334996 in Garfield County Colorado.

Refer to document #699803231 inspection conducted on 6/11/21. Not all previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a previous corrective action date of 9/11/21.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	09/11/2021

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meter runs have been calibrated in the last year		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducer located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	297605	Type:	WELL	API Number: 045-16888 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	297664	Type:	WELL	API Number: 045-16910 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	297665	Type:	WELL	API Number: 045-16911 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	297666	Type:	WELL	API Number: 045-16912 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	297667	Type:	WELL	API Number: 045-16913 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Sediment Traps				
Berms						
Gravel						
		Berms				
		Culverts				
Culverts						
Compaction						
		Compaction				
		Ditches				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Refer to Sign/Markers for corrective actions.	depaoloc	09/14/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803604	Photos for Insp. #699803603	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533005