

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2021

Submitted Date:

09/16/2021

Document Number:

699803619

FIELD INSPECTION FORM

Loc ID 323884	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				Findings: 17 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211084	WELL	PR	05/31/1994	GW	045-06842	UNOCAL GR 31-2	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 9/15/21 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE, Location #323884 in Garfield County Colorado. While there, I observed normal production operations. During this inspection the following compliance issues were observed:

- 1) Horizontal separators includes glycol storage tank. Glycol storage tank is approximately 2'x3'x10' with an approximate capacity of 11 barrels. Glycol storage tank missing required information with a corrective action date of 12/15/21.
- 2) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 9/30/21.

- Location is located in a high priority habitat area all drainages contributed to Parachute creek.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Horizontal separator includes glycol storage tank. Glycol storage tank is approximately 2'x3'x10' with an approximate capacity of 11 barrels. Glycol storage tank missing required information.		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled with Name of operator, Operator's emergency contact telephone number, Tank capacity, Tank contents, and NFPA label or equivalent globally harmonized label.	Date:	12/15/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Separate containment				
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	211084	Type:	WELL	API Number:	045-06842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
		Berms				
		Culverts				
		Compaction				
Ditches						
		Check Dams				
		Sediment Traps				
Compaction	Fail					Location lacks stabilization.
Other	Fail					Insufficient tracking BMP at entrance to location
Gravel	Fail					Gravel insufficient
Sediment Traps						

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations](#)

Date: 09/30/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Refer to Sign/Markers and Storm water for corrective actions.	depaoloc	09/16/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803620	Photos for Insp. #699803619	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533012