

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/14/2021

Submitted Date:

09/14/2021

Document Number:

699304269

**FIELD INSPECTION FORM**
 Loc ID 333133 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		tmouret@p3petro.com	
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241406	WELL	SI	08/01/2020	OW	123-09195	OSKARSON 3	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	weeds will need to be addressed in the near future		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around WH, Properly dispose of oily waste.		
Corrective Action:	Comply with Rule 907.e, New Rule 905.e		Date: 12/14/2020
Type	OTHER		
Comment:	unused electric panel leaning on fence		
Corrective Action:	Comply with Rule 603.f, New Rule is 606		Date: 12/14/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	meter box, electric panel and transformers			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	electric motor			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 241406 Type: WELL API Number: 123-09195 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/27/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0Comment: Submit test information to the COGCC. appears to be plumbed to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/14/2021 at approximately 1140 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Painted Pegasus Petroleum LLC location: Oskarson #3 at API #05-123-09195 in Weld County Colorado. Follow up to Doc #699302553 &amp; 699303852.</p> <p>While there, I observed a wellsite. SI at the time of inspection all valves are closed and the electric power is off.</p> <p>During this inspection the following possible compliance issues were observed and are now delinquent:</p> <p>603.f housekeeping: unused electric panel leaning on fence, CA date 12 14 2020.</p> <p>907.e housekeeping: stained soil around WH, CA date 12-14-2020 .</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	09/14/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402811533	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5531001">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5531001</a>
699304270	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5530995">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5530995</a>