

Inspection Photos
Operator: Simcoe
Facility: 067-06640
Date: 9/16/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass and rubber rabbitbrush.



Photo 3. View of erosional channel leading out of the northern edge of the project area, where wattles are inundated, and banks are eroding and lack stabilization. Wattles are not adequate BMPs here.



Photo 4. View of area in the northwestern corner of the project area where stormwater flows off of the project area, conveying significant sediment loads and inundating BMPs.



Photo 5. View of the reference area, comprised of sagebrush shrubland with open pinyon and juniper woodland and blue grama, squirreltail, four o'clock, and goldenaster in the understory.