

Inspection Photos

API: 055-06219

Operator: PETROGLYPH OPERATING CO

Inspection Date: 9/17/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 1. Facing southeast along the access road. There are noxious weeds along the road (Diffuse knapweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 2. Facing southeast further along the access road. The rock check dams along the road side appear to be controlling erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 3. Facing back northwest on the road adjacent to the location. This erosion channel previously observed was never repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 5. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 6. Facing toward the fill slope. There is sparse vegetation along the fill slope and the plastic netting still remains shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021

Inspection Photos



Photo 7. Facing toward the east side of the location. The vegetation is well established at the eastern portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 9/17/2021