

# Inspection Photos

API: 055-06221

Operator: PETROGLYPH OPERATING CO

Inspection Date: 9/17/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the access road. There are noxious weeds along the road (Diffuse knapweed).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 9/17/2021

## Inspection Photos



**Photo 2.** Facing southeast along the access road toward the location. There are noxious weeds along the road (Diffuse knapweed).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 9/17/2021

## Inspection Photos



**Photo 3.** Facing east toward the location. Perennial vegetation is established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 9/17/2021

## Inspection Photos



**Photo 4.** Facing south toward the location. Perennial vegetation is established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 9/17/2021

## Inspection Photos



**Photo 5.** There is plastic netting debris along the southeast cut slope that still remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 9/17/2021

## Inspection Photos



**Photo 6.** Facing southeast at the south side of the location. The access road continues past the location. This area along the roadside is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 9/17/2021