

Inspection Photos

API: 055-06155

Operator: PETROGLYPH OPERATING CO

Inspection Date: 9/17/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 1. Facing south along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 2. Facing west further along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 3. The road then turns back to the southeast. Areas of the road are stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 4. Facing west along the road. There are some signs of erosion. There are water bars installed along the road to help divert stormwater.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 5. Facing northwest further along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 6. Facing west toward the location. The perennial vegetation has uniformly reestablished at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021

Inspection Photos



Photo 7. Facing southwest toward the location. The perennial vegetation has uniformly reestablished at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06155 | Date: 9/17/2021