

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2021

Submitted Date:

09/23/2021

Document Number:

696105060

FIELD INSPECTION FORMLoc ID 415386 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415416	WELL	SI	06/01/2017	OW	123-31057	DILLARD USX AB 5-15P	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (310217, 415386).
(Well(s): 2: Shut-In | SI).

Refer to Field Inspection Report doc. #696105058 and/or Location ID #310217
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696105058 and/or Location ID #310217 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel w/ barbed wire.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696105058 and/or Location ID #310217 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Shut-down. Protective shed surrounds gas engine.		

Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696105058 and/or Location ID #310217 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.596745,-104.563828	
Comment:	Centralized Battery serves 2 Location IDs (310217, 415386). Refer to Field Inspection Report doc. #696105058 and/or Location ID #310217 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 415416 Type: WELL API Number: 123-31057 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI
Observed production valves shut.
COGCC records indicate last production: 05/2017.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/14/2019Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: --Fluid Type: End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months. Refer to Rule 207.
Submit current Brhd test. Comply w/ Rule 207.
Contact COGCC Engineering.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 09/21/2021 at approximately 16:17 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Dillard USX AB /05-15P Location ID: 415386 Well Name(s): Dillard USX AB 5-15P. API: 05-123-31057. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310217, 415386). (Well(s): 2: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696105058 and/or Location ID #310217 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105061	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539416