

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2021

Submitted Date:

09/07/2021

Document Number:

701101913

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
315416 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 13 Number of Comments
 5 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 51130
 Name of Operator: LOCIN OIL CORPORATION
 Address: 2445 TECHNOLOGY FOREST BD #710
 City: THE WOODLANDS State: TX Zip: 77381

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Nicol, Michael	281-362-8600x116	mnicol@locinoil.com	All inspections
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230794	WELL	PR	08/01/2020	GW	103-08463	N. DOUGLAS CREEK 3-33-1-1	PR

General Comment:
 COGCC Routine Inspection Report Summary
 During this inspection the following compliance issues were observed:
 • Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well. Contents faded and not visible from distance.
 • Battery sign not at tank battery.
 • Dead weed debris on location and access road.
 • Berm built into pit. Erosion of berm ground base and under cutting ground under the tank.
 • Storm water moving sediment and eroding access road from location to road. Access road has storm water erosion and sediment back filled ditches.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access road not maintained. See storm water report.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign not at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 12/07/2021
Type	TANK LABELS/PLACARDS		
Comment:	Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well. Contents faded and not visible from distance.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 12/07/2021
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weed debris on location and access road.		
Corrective Action:	Comply with Rule 606		Date: 09/25/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	90 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth			Base Insufficient	Inadequate
Comment:	Berm built into pit. Erosion of berm ground base and under cutting ground under the tank.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 10/08/2021

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 230794 Type: WELL API Number: 103-08463 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				Sediment in ditches
		Compaction				Erosion of road surface
Compaction						

Comment: Storm water moving sediment and eroding access road from location to road. Access road has storm water erosion and sediment back filled ditches.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/22/2021

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: 39.924764 Long: -108.740671

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: none

Corrective Action: _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402803684	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524903
701101920	Inspection 701101913 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524902