

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2021

Submitted Date:

09/28/2021

Document Number:

699304333

**FIELD INSPECTION FORM**Loc ID 318399 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241226	WELL	TA	12/30/2019	OW	123-09014	1415 CORP UNIT F 1	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	concrete slab for pump jack, unused ancillary equipment.		
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements.		Date: <u>10/28/2021</u>
Type	WEEDS		
Comment:	Dead weeds growing around WH and concrete slab		
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements.		Date: <u>10/28/2021</u>

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	OTHER		
Comment:	unused ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:			Date:

<b>Equipment:</b>				corrective date
Type: Ancillary equipment	# 1			
Comment:	unused Electric panel, meter box and transformers			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	See Inspection Doc # 699304331 for information concerning shared facilities and equipment.					

Corrective Action:		Date:	
<b>Paint</b>			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Comment:			
Corrective Action:	Date:		
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:	Date:		
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:	Date:		

**Inspected Facilities**Facility ID: 241226 Type: WELL API Number: 123-09014 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA, Form 04 TA Doc #401784269 5-16-2019. Well last produced March 2005. This well does have a MIT 12/12/2019. Well is due for another MIT or be produced before 12/12/2021. "Well was found in state of Temporary Abandonment.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 11/12/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: appears to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/28/2021 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">1415 Corp. Unit F #1 at API #05-123-09014 in Weld County Colorado.</p> <p>While there, I observed a wellsite and tank battery, TA at the time of inspection. During this inspection the following possible compliance issues were observed:</p> <p>606 housekeeping: weeds growing around WH, concrete slab, CA date 10-28-2021.</p> <p>606 housekeeping: Unused concrete slab where pump jack would be placed, unused transformers and meter box, CA date 10-28-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	09/28/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304334	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542691">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542691</a>