

TEP
RWF 14-29
Location # 429828



location



location



TEP
RWF 14-29
Location # 429828



location



Lack of stabilization/compaction



TEP
RWF 14-29
Location # 429828



Lack of stabilization/compaction



Lack of stabilization/erosion



TEP
RWF 14-29
Location # 429828



Lack of stabilization/erosion



Lack of stabilization/erosion



TEP
RWF 14-29
Location # 429828



Missing bull plugs/caps on load out lines



Missing bull plugs/caps on load out lines



TEP
RWF 14-29
Location # 429828



**Unused /stored steel and poly pipe near access road
and at right of way**



**Unused /stored steel and poly pipe near access road
and at right of way**



TEP
RWF 14-29
Location # 429828



**Unused /stored steel and poly pipe near access road
and at right of way**



**Unused /stored steel and poly pipe near access road
and at right of way**



TEP
RWF 14-29
Location # 429828



**Unused /stored steel and poly pipe near access road
and at right of way**



**Unused /stored steel and poly pipe near access road
and at right of way**



TEP
RWF 14-29
Location # 429828



**Unused /stored steel and poly pipe near access road
and at right of way**



**Unused /stored steel and poly pipe near access road
and at right of way**



TEP
RWF 14-29
Location # 429828



Location where unused poly and steel piping run under road



Open ended poly that runs up the hill on right of way



TEP
RWF 14-29
Location # 429828



**Unused /stored steel and poly pipe near access road
and at right of way**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RWF 14-29
Location # 429828

3° N

39°29'23" N 107°55'7" W

Parachute, CO

5430 ft Elevation

South East corner of tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources