

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2021

Submitted Date:

10/01/2021

Document Number:

700703313

FIELD INSPECTION FORM

 Loc ID 335066 Inspector Name: Ramsey, Scott On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 21 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284277	WELL	PR	04/13/2006	GW	045-12122	SAVAGE RWF 231-32	PR
284279	WELL	PR	04/13/2006	GW	045-12123	SAVAGE RWF 341-32	PR
284281	WELL	PR	04/13/2006	GW	045-12125	SAVAGE RWF 232-32	PR
284282	WELL	PR	04/02/2007	GW	045-12126	SAVAGE RWF 242-32	PR
286745	WELL	PR	09/11/2014	GW	045-12758	SAVAGE RWF 441-32	PR
286747	WELL	PR	10/03/2014	GW	045-12757	SAVAGE RWF 332-32	PR
286748	WELL	PR	09/15/2006	GW	045-12756	SAVAGE RWF 32-32	PR
286749	WELL	PR	09/15/2006	GW	045-12755	SAVAGE RWF 331-32	PR
286750	WELL	PR	09/15/2006	GW	045-12754	SAVAGE RWF 31-32	PR
286751	WELL	PR	09/15/2006	GW	045-12753	SAVAGE RWF 541-32	PR
286752	WELL	PR	09/15/2006	GW	045-12752	SAVAGE RWF 442-32	PR
286753	WELL	PR	10/31/2007	GW	045-12751	SAVAGE RWF 42-32	PR
286754	WELL	PR	10/03/2014	GW	045-12750	SAVAGE RWF 342-32	PR
286755	WELL	PR	09/11/2014	GW	045-12749	SAVAGE RWF 41-32	PR
286756	WELL	PR	09/15/2006	GW	045-12748	SAVAGE RWF 241-32	PR
286784	WELL	PR	03/18/2008	GW	045-12773	SAVAGE RWF 431-32	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 9/30/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 242-32, at Location # 335066 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/compaction
2. Missing bull plugs/caps on load out lines
3. Four quad unit horizontal separators includes 8 glycol storage tanks, approximately 174" x 33" x 42" = 25 BBLS each, storage vessels contain no labeling to specify capacity or chemical hazard information.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Four quad unit horizontal separators includes 8 glycol storage tanks, approximately 174" x 33" x 42" = 25 BBLs each, storage vessels contain no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Install proper labeling		Date: 01/03/2022
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Missing bull plugs/caps on load out lines (FYI one load bucket has alot of wasps)		
Corrective Action:	Comply with rule 603.i.		Date: 11/01/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pig Station	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	284277	Type:	WELL	API Number:	045-12122	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	284279	Type:	WELL	API Number:	045-12123	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	284281	Type:	WELL	API Number:	045-12125	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	284282	Type:	WELL	API Number:	045-12126	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	286745	Type:	WELL	API Number:	045-12758	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	286747	Type:	WELL	API Number:	045-12757	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	286748	Type:	WELL	API Number:	045-12756	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	286749	Type:	WELL	API Number:	045-12755	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 286750	Type: WELL	API Number: 045-12754	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286751	Type: WELL	API Number: 045-12753	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286752	Type: WELL	API Number: 045-12752	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286753	Type: WELL	API Number: 045-12751	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286754	Type: WELL	API Number: 045-12750	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286755	Type: WELL	API Number: 045-12749	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286756	Type: WELL	API Number: 045-12748	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 286784	Type: WELL	API Number: 045-12773	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [1. Location shows signs of lack of stabilization/compaction](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 11/01/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703320	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545713