

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2021

Submitted Date:

09/27/2021

Document Number:

693505491

FIELD INSPECTION FORMLoc ID 335697 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275611	WELL	PR	07/01/2021	GW	001-09528	STANDLEY 6-2	PR

General Comment:

Inspection due to operations on site.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: 2" flow line off well head leaking on hammer union.

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 09/26/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 275611 Type: WELL API Number: 001-09528 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/30/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Saturday September 25, 2021 at approximately 9:30, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Standley 602</p> <p>Operator: KP Kaufman</p> <p>API#: 001-09528</p> <p>County: Adams</p> <p>While there, I observed a well site and production facility with work over rig and blow down equipment on site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Mechanical issue: Rule 608 e Corrective action date of 9-26-21 See video.</p> <p>Weather conditions: Clear and dry</p> <p>At time of inspection at approx. 9:30AM I call KPK emergency contact number to report a leaking 2" hammer union on the Standley #6-2. A short time after that KPK supervisor Manny called me to inform me he was on his way to address the issue. At approx. 12:00PM Manny called back to report he has fixed issue. Standley 8-3 is undergoing blow down operations to install BOP at time of inspection blow down crew was not there and bop was not installed.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	09/27/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402823602	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540885
693505492	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540431
693505493	video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540432