

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Excavation surrounded by snow fence; appears adequate for location at time of inspection		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240989 Type: WELL API Number: 123-08777 Status: SI Insp. Status: EI

Facility ID: 478617 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC Inspection of ongoing remedation project 18950. COGCC did not observe apparent changes since previous inspection of split sampling with Operator. Operator to submit Form 27 Supplemental as required by previous inspection and repeated below.

Corrective Action: Corrective Action from previous inspection: Next Form 27 Supplemental is due 9/30/2021 with a quarterly update that includes: 1. All soil and water analytical data collected to date; 2. Results of root cause of Spill investigation include any effort undertaken to repair casing leak noted in previous inspections; 3. Schedule for continued necessary investigation or remediation and timeline for completion of all site activity related to remediation of the Release.

Date: 10/18/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402823603	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540886
693700868	Jillson A 1 Photos 9-24-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540469