

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/27/2021

Submitted Date:

09/27/2021

Document Number:

699104528

**FIELD INSPECTION FORM**
 Loc ID 437416 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Marty Krautschun		mkrautschun@bonanzacrk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
462948	WELL	WO	07/22/2019	OW	123-49895	Latham 41-44-14HNC	WO

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	Frac		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Frac sand on the ground around the frac cans needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606		Date: 09/29/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 462948 Type: WELL API Number: 123-49895 Status: WO Insp. Status: WO

**Well Stimulation**Stimulation Company: Nextier Completion SolutionsStimulation Type: HYDRAULIC FRAC**Observation:**

Other: \_\_\_\_\_

Maximum Casing Recorded: 7920 PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: At the time of inspection I observed a Stimulation Operations on the Latham 41-44-14HNC. The Contractor NexTier Completion Solutions, were Fracking.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>  On Monday 9/27/21 at approximately 1121hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Latham 41-44-14HNC of Bonanza Creek Energy, at API # 05-123-49895 in Weld County, Colorado.  At the time of inspection I observed a Stimulation Operations on the Latham 41-44-14HNC. The Contractor NexTier Completion Solutions, were Fracking.  During this inspection the following possible compliance issues were observed:  Frac sand on the ground around the frac cans needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 9/29/21  See attached photos.  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	burnsa	09/27/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402823604	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540887</a>
699104529	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540807">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540807</a>