



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: [Stained soil/mechanical issues near wellhead, pumping unit motor, separator, front, and back of tanks. Weeds are sprayed and dead.](#)

Corrective Action: [Comply with COGCC housekeeping rules](#)

Date: 06/21/2020

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: [Gas motor](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 2

Comment: [ECD, separator](#)

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: [Calibrated 7/21](#)

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Gas meter run/separator automation](#)

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 202429 Type: WELL API Number: 001-07834 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 08/14/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: Annual bradenhead test may need to be performed soon.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On 9/21/21 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at:  Well Name- May 32-6  Company Name- Renegade oil and gas  API- 05-001-07834  In Adams County Colorado.  While there, I observed Producing well.  This is a follow up inspection for Document # 687400821  Corrective actions are delinquent.  During this inspection the following possible compliance issues were observed:  Stained soil/mechanical issues near wellhead, pumping unit motor, separator, front, and back of tanks. Weeds are sprayed and dead.  Comply with COGCC housekeeping rules 6/21/20  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	medinaj	09/21/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402823605	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540888">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540888</a>
699503189	Inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540520</a>