

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2021

Submitted Date:

09/28/2021

Document Number:

690008483

### FIELD INSPECTION FORM

Loc ID 307124 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10379  
Name of Operator: HARBURG\* RUDOLPH W  
Address: 1020 MAPLETON AVE  
City: BOULDER State: CO Zip: 80304

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Harburg, Rudy	(303) 931-8099	rudy.harburg@gmail.com	
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216916	WELL	PR	01/01/2013	GW	069-06103	WESTWARD 2	TA

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Sign not posted or information inaccurate at oil and gas location.		
Corrective Action:	Install sign to comply with Rule 605.a	Date:	09/06/2021

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Propane Tank At Battery.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Weeds at wellhead and battery		
Corrective Action:	n: Comply with Rule 606	Date:	08/13/2021

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No  
 Comment:   
 Multiple Spills and Releases?

**Equipment:**

	#	corrective date
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

<b>Paint</b>	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shared with crude oil tank.				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.372920,-105.065880
Comment:					Date:
Corrective Action:					Date:

<b>Paint</b>	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment: Secondary containment is not sufficiently impervious to contain spilled or released materials.				Date:
Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure.				Date: 09/06/2021

**Wells Served By Facilities Above**

**AirsID**

API Number
069-06103

API Number	AirsID
------------	--------

<b>Venting:</b>	
Yes/No	YES
Comment:	Well is not closed to atmosphere
Corrective Action:	Close well to atmosphere as directed by Rule 434.b.(1)
Date: 09/29/2021	

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 216916 Type: WELL API Number: 069-06103 Status: PR Insp. Status: TA

**COGCC Comments**

Comment	User	Date
<p>Follow up inspecton.</p> <p>On Tuesday, September 28, 2021 at 10:59, I, Craig Carlile conducted an on-site follow up inspection at: WESTWARD-65N69W25SWSE, location number: 307124            Operated by: HARBURG* RUDOLPH W 10379            While there I observed: Audible lead at wellhead, requested FLIR inspection resources to be dispatched to location to accurately document gas leakage from wellhead master valve. Previously cited weed, signage and unused equipment corrective actions have not been accomplished.            Weather: Skies: Partly Cloudy, Wind: Calm, Temp 72 Degrees F            Photos from previous inspection on August 5, 2021 and from September 28, 2021 demonstrate the corrective actions have not been accomplished.            Comments from previous inspection are repeated below:            "On Thursday, August 5, 2021 at 10:23, I, Craig Carlile conducted an on-site inspection at location number: 307124, location name: WESTWARD- 65N69W25SWSE            Operated by: HARBURG* RUDOLPH W 10379            While there I observed: Audible leak at wellhead, lack of signage at wellhead and battery, uncontrolled weeds at wellhead and battery, unused equipment at battery (propane tank)            Note: Last production report available in COGCC data base 12/1/2015, documents in review include NOAV actions addressing this issue.            Additionally, a Form 6(N) has been submitted and approved with a status date of 7/19/2021,            no evidence of plugging activity evident at time of inspection.            Weather: Skies: Clear, Wind: Calm, Temp 76 Degrees F"            This is a summary of the inspection report.</p>	carlilec	09/28/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402825004	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542031">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542031</a>
690008484	Current Inspection.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542026">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542026</a>
690008486	August 5, 2021 Inspection.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542027">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542027</a>