

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2021

Submitted Date:

09/28/2021

Document Number:

694500371

FIELD INSPECTION FORM

Loc ID: 316764 Inspector Name: NEIDEL, KRIS On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 6720
Name of Operator: ROBERT L BAYLESS PRODUCER LLC
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
thomas, john	505-326-2659	jthomas@rlbayless.com	
Trujillo, Helen		htrujillo@rlbayless.com	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

On 9/15/2021 COGCC staff, Kris Neidel was present to observe soil sample collection and environmental inspection. Soil samples were collected from a former flare pit at the Dry Creek Federal 1-14. Weather was 78 degrees and sunny, the well is located in a small narrow, canyon. Pit facility id #480784 was created administratively to document the location of flare pit. Pit is being closed as a part of REM #19966. The following was observed: a cyclone fence with barbwire was around ¾ of the pit area. Part of the fence was removed to allow for the removal of soil from pit area. Samples were collected from the pit bottom and pit walls, soil had a strong hydrocarbon odor and staining. (see photo log for more description) There is a stockpile of soil on the pad that was reportedly excavated from the pit. The pit area is on a slope toward Sage Creek. Sage Creek is approximately 70 feet from the edge of former flare pit. Sage Creek was completely dry at the time of inspection; the pit is approximately 10 feet deep and 25feet around. The E&P waste soil excavated from the pit area is being stored on a tarp on location, this soil was sampled for waste disposal characterization. Corrective Action: comply with previous inspection Corrective Actions, within 21 days of receiving sample results of soil sampling, submit on a supplemental Form 27. See Photos.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Flare Lined: NO Pit ID: 480784 Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment: Pit is not currently in use, it is being closed. Pit ID was created by COGCC staff. At time of inspection, it was apparent that impact remains in soil after initial excavation. Groundwater appears to be shallow in the area

Corrective Action: Within 21 days of receiving sample results of soil sampling, submit on a supplemental Form 27.

Date: 11/30/2021

Fencing:

Fencing Type: Safety Fencing Condition:

Comment: mment: fence was removed to allow work on pit

Corrective Action: Action prevent wildlife from entering pit

Date: 11/30/2021

Netting:

Netting Type: Netting Condition:

Comment: no netting

Corrective Action:

Date: _____

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402825716	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542543
694500372	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542532