

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2021

Submitted Date:

09/28/2021

Document Number:

700703294

FIELD INSPECTION FORM
 Loc ID 311612 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269872	WELL	PR	07/02/2012	GW	045-09416	LAST DANCE 12-2	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 9/28/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Last Dance 12-2, at Location # 311612 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

C/A's (location stabilization, tracking, tank missing info, staining and debris) from previous inspection document # 700702390 have been completed. C/A (cut slope stabilization has not been completed from previous inspection document # 700702390.

During this inspection the following compliance issues were observed:

1. One load out line is missing cap/bull plug (broken)
2. Cut slope still shows signs of erosion/lack of stabilization from previous inspection (C/A date remains 4/9/2021)
3. ECD is unused/stored equipment
4. Horizontal separators units includes glycol storage tanks, storage vessels have labeling, but is missing capacity and one label is illegible. Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Horizontal separators units includes glycol storage tanks, storage vessels have labeling, but is missing capacity and one label is illegible.		
Corrective Action:	Provide legible labeling	Date:	12/28/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	ECD is unused/stored equipment		
Corrective Action:	Remve unused/stored equipment	Date:	10/28/2021
Type	OTHER		
Comment:	One load out line is missing cap/bull plug (broken)		
Corrective Action:	Comply with rule 603.i.	Date:	10/28/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date	
Type: Ancillary equipment	# 2				
Comment:	500 gallon methanol tanks in metal containments				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 3				
Comment:					
Corrective Action:					Date:
Type: Pig Station	# 2				
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Chemical tank in plastic containment				
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 1				
Comment:	See storage of equipment				
Corrective Action:					Date:
Type: Bird Protectors	# 9				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	200 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	269872	Type:	WELL	API Number:	045-09416	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. Cut slope still shows signs of erosion/lack of stabilization from previous inspection (C/A date remains 4/9/2021)

Corrective Action: Instal or maintain BMP's

Date: 04/09/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402825891	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542710
700703299	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542700