



- Photo 1 –





- Photo 2 – Tank battery, view northeast, wellhead in the background





- Photo 3 – South end of tank battery, view west, erosion control needed





- Photo 4 –





- Photo 5 – View north, weeds on access road need mowing or other control





- Photo 6 – Well sign



- Photo 7 – Wellhead, view east





- Photo 7 – South side of wellhead, weeds, view east





- Photo 9 – East side of well area, weeds in the background, view north





- Photo 10 – oily soil under motor





- Photo 11 – Flywheel guard off, weeds on north side of pumpjack